Offshore Marine Surveyors

1661 S.W. 23RD Ave., Ft. Lauderdale, Florida 33312 Tel (954) 587-5879 Fax (954) 316-5149

Motor Vessel Condition & Valuation Survey

Vessel Name: "TowBoat US SeaArk Barge"

File No: 1580093 Survey Date: 08/18/15 Builder: SeaArk Marine
Client: Model Year: 1996 Model: 30' Barge
Offshore Marine Towing Year Built: 1996 Official #: N/A

601 NE 28th Ct. **Hull Type:** Modified-V **HIN:** SAMA0712I696

Pompano Beach, FL 33064 Construction: Aluminum Power: (2) 115hp Johnson OB's

Intended Use: Commercial **Eng. SN:** (p) G04112691

(s) G04112765

Description: Outboard powered aluminum barge with red hull, gray decks, white superstructure

and rails, black bottom.

LOA: 30' **Draft:** Approx. 3' **Beam:** 10'6" **Displacement:** Approx. 5,900lbs

Fuel Tank (s), Material: (1) Aluminum Capacity: 75 gallons

Location/Scope of Survey: The vessel was surveyed afloat at Lauderdale Marina in Fort Lauderdale, Florida. AC & DC systems were proven. Safety gear was inspected.

Surveyor's Remarks

The vessel was found to be structurally and mechanically sound. Her machinery components, fuel system, wiring, and other major systems, appear serviceable and have been installed in accordance with applicable standards and regulations. No deficiencies were found.

Vessels overall condition: Excellent **Approximate present value:** \$75,000.00.

Approximate replacement value: \$125,000.00.

Recommendations for compliance with U.S. Coast Guard regulation, Title 33 Code of Federal Regulations, Title 46 United State Code, American Boat and Yacht Council Recommended Practice, National Fire Protection Association Standards, and Good Marine Practice:

None

Details of Inspection

Safety Gear

Fire extinguishers: There are (2) ABC rated units located in the wheelhouse. One unit

is new, the gauges on both show charged. Certification is required annually.

Bilge Pumps: Electric manual/auto: Amidships/Rule 1100gph Function: Good

Electric manual/auto: Aft/Rule 3700gph Function: Good Electric manual/auto: Aft/Rule 1000gph Function: Good

Life Jackets, No/type: (6) type II, stored in the aft storage compartment.

Throwable: (1) type IV, secured aft of the wheelhouse.

Anchor: (2) Danforth with chain and nylon rode. Both are stored in the aft storage

compartment.

Distress Signals: Stored in the aft storage compartment. Expiration date 3/18.

First Aid Kit: Stored in the aft storage compartment.

Horn: Air/electric Function: Good

Oil Discharge & Trash Disposal Placards: Yes

Navigation Gear

Running/Anchor Lights: Good

Towing Lights: Good Strobe Lights: Not found Compass: Not found

VHF Radio: Standard Horizon Matrix GX2000 AIS/GPS Function: Good Private Communication System: Motorola XPR 4550 Function: Good

Equipment

Containment boom Numerous dock lines Jumper cables Deck lights

Hull and Structure

Hull Construction: Welded aluminum

Bottom: Welded aluminum, inspected form the interior only. The plating and welds appear to be

in good condition and show no evidence of galvanic wasting.

Frames/Bulkheads/Stringers: Welded aluminum, appear sound.

Topsides: Welded aluminum, generally blemish free and in good condition.

Deck Construction: Welded aluminum, with non-skid, good

Bonding System: There are zincs on the hull and engines. The vessel is also equipped with a

galvanic isolator.

Through-Hull Fittings: Metallic above and below the waterline. The only below water thru-

hull is the transom drain plug. All appear serviceable.

Hatches: Watertight, good

Windows: Good, no evidence of leaking found. **Deck Hardware:** Secure and in good condition.

Scuppers: Adequate

Bilges: Clean with good access.

Machinery

Engines, Mfg: (2) Johnson 115hp 2 stroke outboards **Fuel:** Gas

Engine Model #: (p) J115SXEDR (s) J115SXEDR

Engine SN: (p) G04112691 (s) G04112765

Year of Manufacture: 1996 **Hours Shown:** (p) 161 (s) 14

Appearance: The engines appear to be in good condition.

Propellers: 3 blade, good

Steering System:Sea Star hydraulicFunction: GoodControls:Dual handle cable with trim control.Function: Good

Gauges: Analog

Power Tilt & Trim: Good

Function: Not proven
Function: Good

Fuel System

Fuel Tank(s): (1) Aluminum, located below deck, capacity 75 gallons. The tank appears

serviceable and no evidence of leaking was found.

Fuel Fill Location: Side deck Fuel Lines: Approved type

Grounded: Yes

Fuel Filters: Fuel/water separators

Comments: The system appears serviceable.

Electrical System, DC

Nominal Voltage: 12vdc

Battery Switches: (2) Approved type

Batteries, Quantity/Type: (2) group 24 wet cell. Both batteries are covered and secured. **Panel Location:** Helm, all breakers/switches are labeled and appear to be in good condition.

Meters: Volt at helm

Circuit Protection: Breakers & fuses, all circuits appear to have overload protection.

Wiring: Thermoplastic, marine grade, properly routed and secured.

Comments: The system appears serviceable.

Electrical System, AC

The AC system consists of 15 amp inlet fitting to power the Crown 60 amp battery charger. The system appears serviceable.

Deck Layout

The wheelhouse is centerline aft. Forward of the wheelhouse is a large cargo hold. Aft is a below deck storage compartment with watertight hatch.

Every reasonable effort has been made by this surveyor to provide an accurate report. However, the examination was made without removing any permanent structure or fixture, or dismantling components or equipment. It is a statement of my opinion based on conditions found and is not a guarantee or warranty of the condition of the vessel or its equipment.

Signed without prejudice, Member:

By /Paul P. Slawel/ Society of Accredited Marine Surveyors (AMS#518)

Paul Peter Slawek, AMS













